


11BNC 50-7-1c

M 5:1



21.6.73 /3.




HUBER + SUHNER AG  
9100 Herisau

4.13.6371 a


Diese Zeichnung ist unser geistiges Eigentum und darf ohne unsere ausdrückliche Einwilligung weder kopiert, vervielfältigt, noch Dritten oder Konkurrenzfirmen zugänglich gemacht werden. (Art. 12 B.G.)

This drawing is copyright. Information contained thereon is supplied in confidence and must not be used for any other purpose than which it was supplied, or be reproduced without written permission of the owners.

11 BNC 50-7-1 11 BNC 75-7-1  
 11 BNC 50-7-2 11 BNC 75-7-2



M. 4:1

 HUBER + SUHNER AG  
 9100 Herisau

3.13.07817\_1

b

Erstellt	23.11.95	Kurz/Vision
Geprüft	L. Z. G. / P. G. H. S. G.	
Freigebe	W. G. S. / P. G. H. S. G.	

# Assembly instruction Series C, N, J B No. 3008

## Tools and materials required:

Stanley blade  
Scissors  
Soldering iron  
Solder

Spanner 16 mm (74 Z-0-0-3)

This connector is supplied in 9 (10) parts

Suitable cables e. g.:

Centre contact:

Braid:

Straight cable connectors for flexible cables

Cable entry: Screw-type

Connector types: (e. g.)

11 C-50-7-4c

21 C-50-7-2c

24 C-50-7-2c

11 N-50-7-4c

21 N-50-7-6c

24 N-50-7-6c

11 J-75-7-2c

21 J-75-7-2c

RG 213/U

RG 213/U

RG 213/U

soldered

soldered



soldered

screwed

screwed

screwed

\* supplied with types 24 C... and 24 N... only




Slide nut A, washer B and gasket C onto cable. Prepare cable according to diagram (6,5 mm for angle connectors).

**CAUTION: Do not damage braid!**


Cables with double braid: Remove 9 mm (7 mm for angle connectors) of jacket.

Armoured cables: Slide two-piece FK-armor-clamp on cable instead of nut A.

Remove 29 mm of armour (27 mm for angle connectors).




Push braid back and widen it slightly but do not comb it out. Cut back dielectric 5 mm perpendicular to cable axis (3 mm for angle connectors).



Taper braid towards center conductor.


Position braid clamp D so that its shoulder fits against cable sheath.



Fold back braid over clamp D and trim overlapping braid. Position bushing E, insulator F and gasket L.

Heat inner contact G using a soldering iron (approx. 250 W) and flow small amount of solder into bore.

Push cable inner conductor into bore, immediately remove soldering iron to prevent melting of the dielectric.




Push prepared cable into connector body K, with front part of insulator H, and tighten nut A.

Torque 10 Nm value.

Do not rotate cable in connector body.

Armoured cable: Finally screw on and tighten armour clamp.

For cable assemblies subjected to particular tensile strength, connectors can be fitted with the GUK-cable clamping. Please ask for data leaflets.



SUHNER's skilled staff and specialised equipment are available to carry out complete R. F. lead-assembly on your behalf. We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.



**HUBER+SUHNER LTD. CH-9100 HERISAU**

Deutscher Text: siehe Rückseite